



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6796
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L01-22

Date: 22 MARCH 2001

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-ET-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL PORT SANILAC HARBOR

1. Condition surveys performed within the Federal navigation channel at Port Sanilac Harbor, Michigan during May - August 2000, indicate shoaling as shown on the back of this sheet. Dredging scheduled for the 2001 navigation season has been cancelled. (Update 23 May 2001)
2. Vessel operators should use caution when navigating within this area.
3. All inquiries should be addressed to CELRE-ET-OT-T and should refer to Notice to Navigation Interests No. L01-22. Internet address: <http://huron.lre.usace.army.mil/OandM/o&m.html>

RICHARD J. POLO, JR.
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2001.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: MAY - AUGUST 2000
 gjpsen.bmp

Soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean water Level at Father Point, Quebec, IGLD, 1955.

Shoals indicate least available depth below I.G.L.D.

PORT SANILAC HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 22 MARCH 2001

U.S. Army Engineer District, Detroit

